



HUSQVARNA BATTERY SERIES

HOW LONG WILL THE BATTERY LAST?

WORKING TIME ON ONE CHARGE



APPLICATION	PRODUCT NAME	BATTERY														
		BLi950X	BLi550X	BLi300	BLi200X	BLi200	BLi100	BLi30	BLi20	40-B140	BLi10	40-B70				
CHAINSAWS																
Take down / removal	540i XP® ****	12 h	6 h	3 h 30 min	2 h	2 h	1 h	3 h	1 h 30 min	1 h 30 min	45 min	45 min				
	T540i XP® ****															
Pruning in tree	540i XP® ****	17 h 30 min	9 h	5 h 30 min	3 h	3 h	1 h 30 min	4 h	2 h	2 h	1 h	1 h				
	T540i XP® ****															
	535i XP®															
	T535i XP®															
Pruning	540i XP® ****	7 h 30 min	3 h 45 min	2 h 15 min	1 h 15 min	1 h 15 min	40 min	1 h 45 min	1 h	1 h	30 min	30 min				
	535i XP®				45 min	45 min		1 h 50 min								
	340i				1 h 15 min	1 h 15 min		1 h 50 min								
	330i				45 min	45 min		1 h 50 min								
	120i				3 h	1 h 30 min		—					35 min	35 min	—	—
	540i XP® ****				3 h 30 min	1 h 45 min		—					30 min	30 min	—	45 min
Log cutting	535i XP®	4 h	2 h	1 h	35 min	35 min	15 min	45 min	30 min	30 min	15 min	15 min				
	340i				35 min	35 min		45 min								
	330i				35 min	35 min		45 min								
	540i XP® ****				18 h 45 min	9 h 30 min		5 h 30 min					3 h	3 h	1 h 30 min	4 h 30 min
Carpentering	535i XP®	20 h 30 min	10 h 15 min	5 h 30 min	3 h	3 h	1 h 30 min	4 h 30 min	2 h 30 min	2 h 30 min	1 h 15 min	1 h 15 min				
	340i							4 h 30 min								
	330i							4 h 30 min								
POWER CUTTER																
Cutting concrete garden plates, 40 mm	K 535i			40 pcs	20 pcs	20 pcs										
Cutting roof tiles	K 535i			165 pcs	85 pcs	85 pcs										
Cutting granite, 70 mm	K 535i			10 pcs	6 pcs	6 pcs										
Cutting floor tiles, 7 mm	K 535i			240 pcs	140 pcs	140 pcs										
POLE SAWS																
Pruning	530iPT5	11 h 30 min	5 h 45 min	3 h 30 min	2 h	2 h	50 min	2 h 50 min	1 h 30 min	1 h 30 min	40 min	40 min				
	530iPT4															
	115iPT4															
FORESTRY CLEARING SAW																
Clearing	530iPX	8 h 15 min	4 h 15 min	2 h 30 min	1 h 20 min	1 h 20 min	40 min	2 h	1 h	1 h	30 min	30 min				
BRUSHCUTTERS																
Clearing	535iFR ****	3 h 20 min	1 h 35 min	1 h	30 min	30 min		45 min	20 min	20 min						
Tough grass cutting	535iRX ****	2 h 25 min	1 h 5 min	45 min	25 min	25 min	—	35 min	15 min	15 min	—	—				
	535iRX ****															
	535iFR ****															
Tough grass cutting	535iRX ****	1 h 50 min	50 min	30 min	15 min	15 min	—	20 min	10 min	10 min	—	—				
	535iRX ****															
	535iFR ****															
TRIMMERS																
Tough grass cutting	520iRX	4 h 15 min	2 h	1 h 15 min	40 min	40 min	20 min	60 min	30 min	30 min	15 min	15 min				
	520iLX	2 h 50 min	1 h 20 min	50 min	30 min	30 min	15 min	40 min	20 min	20 min	10 min	10 min				
	325iLX	3 h 45 min	1 h 45 min	1 h	35 min	35 min	20 min	50 min	30 min	30 min	15 min	15 min				
	315iC	3 h 45 min	1 h 45 min	1 h	35 min	35 min	20 min	50 min	30 min	30 min	15 min	15 min				
Light grass cutting	520iRX	8 h 15 min	4 h 15 min	2 h 15 min	1 h 20 min	1 h 20 min	40 min	1 h 50 min	1 h	1 h	30 min	30 min				
	520iLX	5 h 40 min	2 h 50 min	1 h 40 min	50 min	50 min	30 min	1 h 15 min	45 min	45 min	20 min	20 min				
	325iLX	6 h	3 h	1 h 45 min	1 h	1 h	—	1 h 25 min	50 min	50 min	25 min	25 min				
	315iC	6 h	3 h	—	—	—	—	—	1 h	1 h	30 min	30 min				
	115iL	5 h 30 min	3 h	—	1 h 15 min	1 h 15 min	40 min	—	—	1 h	1 h	30 min	30 min			

CHARGING TIME FOR DIFFERENT BATTERIES AND CHARGERS



	CHARGING CYCLES UP TO	QC500	
		CHARGING LEVEL	CHARGING LEVEL
		80%	100%
BLi950X	1500	1 h 40 min	2 h 20 min
BLi550X	1500	1 h	1 h 25 min
BLi300	1500	35 min	1 h
BLi200X/BLi200	1500	30 min	50 min
BLi100	1500	30 min	50 min
BLi30	600	30 min	50 min
BLi20	600	25 min	40 min
40-B140	600	25 min	40 min
BLi10	600	25 min	40 min
40-B70	600	25 min	40 min
QC330			
		80%	100%
BLi950X	1500	3 h	4 h 5 min
BLi550X	1500	1 h 40 min	2 h 5 min
BLi300	1500	55 min	1 h 20 min
BLi200X/BLi200	1500	30 min	50 min
BLi100	1500	30 min	50 min
BLi30	600	45 min	1 h 5 min
BLi20	600	25 min	40 min
40-B140	600	25 min	40 min
BLi10	600	25 min	40 min
40-B70	600	25 min	40 min
QC250			
		80%	100%
BLi300	1500	1 h 5 min	1 h 30 min
BLi200X/BLi200	1500	35 min	55 min
BLi100	1500	30 min	50 min
BLi30	600	1 h	1 h 20 min
BLi20	600	30 min	45 min
40-B140	600	30 min	45 min
BLi10	600	25 min	40 min
40-B70	600	25 min	40 min
QC80 / QC80F			
		80%	100%
BLi300	1500	4 h	4 h 20 min
BLi200X/BLi200	1500	2 h 25 min	2 h 40 min
BLi100	1500	1 h 5 min	1 h 25 min
BLi30	600	3 h 15 min	3 h 35 min
BLi20	600	1 h 50 min	2 h 10 min
40-B140	600	1 h 50 min	2 h 10 min
BLi10	600	50 min	1 h 10 min
40-B70	600	50 min	1 h 10 min

N/A = Values were not available at time of printing. -- = Not recommended
 The runtimes are up-to times and correspond to work time using save™. actual work, basic maintenance and movement/climbing needed for generic operations.
 Given guidelines are indicative only and may not always be repeatable from one setting to another.
 *Requires BLi backpack batteries. **Requires backpack battery / battery belt FLEXI. ***Requires adapter plate and battery adapter for use with backpack battery.
 **** full capacity only provided by BLi200X or BLi300
 ***** run time refers to the use of 2 pcs BLi batteries
 Recommended battery
 Best option

Required battery temperature for charging: min. 5 °C max. 40 °C